INFORMATION REPORT INFORMATIÓN REPORT

CENTRAL INTELLIGENCE AGENCY

BJECT Observations in the DATE DISTR. 30 March 1940 50X1-HUM NO. PAGES REFERENCES THE OF				C- O- N	- F- I-D-E-N-	-T-I-A-L			50X1-HUM
NO. PAGES REFERENCES 50X1-HU 50X1-HU TE ACQ.	OUNTRY	USSR	(Odesskaya	Oblast)		REPORT			
NO. PAGES REFERENCES 50X1-HU 50X1-HU TE ACQ.	JBJECT	Намро	m of Mess		s in the	DATE DISTR	. 30	March	1 9 &ひ 50X1-HUM
TE OF FO. ACE & 50X1-HU		narbo	r or oness	a		NO. PAGES			1
TO OF FO. ACE & 50X1-HU						REFERENCES	3		
ACE & 50X1-HU	ATE OF								50X1-HU
SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE.	ACE &								50X1-HUN
		sc	DURCE EVALUA	ATIONS ARE DE	FINITIVE. APP	RAISAL OF CON	ITENT IS TE	NTATIVE.	

C-O-N-F-I-D-E-N-T-I-A-L

STATE X ARMY X NAV# X AIR X N9A X FBI NIC X

(Note: Washington distribution indicated by "X"; Field distribution by "#")

C-O-N-F-I-D-E-N-T-I-A-L

C-O-N-F-I-D-E-N-T-I-A-L

Observations include the following: port controls; Voyennyy Mole and New Mole undergoing repairs: two MTBs; two possible KRONSHTADT-class submarine chasers,

two submarines; and two vessels resembling submarine chasers,

An annotated sketch map is included.

Sanitized Copy Approved for Release 2010/08/03: CIA-RDP80T00246A051900160001-8

C-O-N-F-I-D-E-N-T-I-A-L

50X1-HUM

COUNTRY	USSH (Ukrainian SSR)	REPORT		
SUBJECT	Observations Made in Odessa	DATE OF REPOR	24 AUG 1959	50X1-H
		NO. OF PAGES	4	50X1-H
		REFERENCES)
DATE OF				
PLACE & DATE ACQ.				50X1-HU
	EVALUATIONS ARE DEFINITIVE. APPRAISAL OF	CONTENT IS TENTATIVE.	NOTE FOREGOING EXI	
5 ;	There were four or five large pil they amounted to about 25,00			

,	, at
,	C-O-N-F-I-D-E-N-T-I-A-L
	2 🖼
	lifting capacity each, were being used in repair work of the New Mole, on the side facing Cabotage harbor. Another crane, about half a ton lifting capacity, was used for repair work which was progressing at a very slow pace. There was a dredger in operation at the head of Voyennyy Mole (see position 4 on sketch), and other repair work was being done at position 5. There is a refrigerated building approximately 60 x 12 x 20 meters, which is used for storage (see position 8). A refrigerated ship was unloading various food stuffs in front of the building. Near this ship there were two floating cranes of 40 or more tons lifting capacity. Along the base of Cabotage harbor there were ten electric cranes on tracks of five to ten tons lifting capacity each.
	Pratique Harbor
Ď., '	The following vessels were observed in Pratique Harbor:
•	Two MTBs which had been pulled ashore;
1	A small floating dock, na -19, approximately 30 meters long and 10 meters wide, with two naval auxiliary vessels on it. This floating dock can accommodate vessels up to approximately 1,500 tons (position 6 on sketch);
:	Two /KRONSHTADT-class? subchasers
	a SKORYY-class? destroyer 50X1-HU
•	


Unidentified naval vessel, pendant number 379;

Two identical naval vessels, resembling submarine chasers

Sanitized Copy Approved for Release 2010/08/03: CIA-RDP80T00246A051900160001-8

art.

C=O-N-F-I-D-E-N-T-I-A-L



50X1-HUM

50X1-HUM